

MJM INTERNATIONAL CORPORATION

418-OR-3TW

WARNING NOT SECURING ALL PARTS PROPERLY CAN CREATE A SERIOUS SAFETY HAZARD.

IDENTIFY ALL COMPONENTS TO START ASSEMBLY PARTS INCLUDED FOR WALKER

- PARTIALLY ASSEMBLED FRAME.
- □ 4 CASTERS (2 WITH BRAKE & 2 NON BRAKE
- □ SIDE OUTRIGGERS WITH ANTI--TIPS--2
- □ SIDE RAILS--- 2 MAKE UP THE ARM SECTIONS
- □ SPRING LOADED FLAT GATE---1 IS CONNECTED TO ONE SIDE RAIL
- □ PVC BACK --1
- ☐ MESH SLING-- 1
- SEAT CUSHION--1
- SAFETY BELT-- 1
- CLAMP LOCKS FOR ADJUSTABLE HEIGHTS-- 4 PLACED ON BOTTOM FRAME
- REINFORCEMENT RINGS -- 4 ATTACHED TO BOTTOM FRAME IN CORNERS



NOTE: A PHILLIPS SCREWDRIVER OR A CORDLESS HAND DRILL IS REQUIRED TO TIGHTEN/SECURE ALL SCREWS.

STEP 2



REMOVE SCREWS FROM REINFORCEMENT RINGS

STEP 3



INSERT CASTERS --PLACE BRAKE WHEELS ON THE REAR OF THE WALKER

STEP 4



SECURE CASTERS WITH SCREWS PROVIDED USING PILOT HOLE AS REFERENCE

STEP 5



INSERT OUTRIGGERS ON THE SIDE OF THE BOTTOM FRAME BY MATCHING COLOR CODED DOTS AND SECURE USING SCREWS PROVIDED USING PILOT HOLES AS REFERENCE

STEP 6



REMOVE SCREWS FROM AREA BY SEAT SECTION

STEP 7-1



INSERT SIDE RAILS BY MATCHING COLOR CODED DOTS.

MJM International Corporation www.mjminternational.com

1-800-270-6199

Fax: (956) 781-5552 hmoroles@yahoo.com

REV. B Date: 17-02-11 Page 1 of 2

MJM INTERNATIONAL CORPORATION

JM INTERNATIONAL COR 418-OR-3TW

WARNING NOT SECURING ALL PARTS PROPERLY CAN CREATE A SERIOUS SAFETY HAZARD.

STEP 7-2



INSERT SIDE RAILS BY MATCHING COLOR CODED DOTS .

STEP 7-3



SECURE SIDE RAILS USING SCREWS PROVIDED AND PILOT HOLES AS REFERENCE

STEP 8



INSERT MESH SLING WITH PVC BACK TOWARDS SEAT SECTION ON TOP OF SIDE RAILS, SECURE USING SCREWS PROVIDED AND PILOT HOLES AS REFERENCE.

STEP 9



ADJUST MESH SLING AS NEEDED

STEP 10



SECURE FLAT GATE ON FRONT SIDE RAIL USING PILOT HOLE PROVIDED

STEP 11



418-OR-3TW COMPLETELY ASSEMBLED

NOTE: CLAMP LOCKS CAN BE REMOVED TO ADJUST THE HEIGHTS ON THE WALKER.

NOTE: SECURE SAFETY BELT ON THE FRONT GATE AND SECURE SEAT CUSHION WITH VELCRO

NOTE: CASTERS/CLAMP LOCKING SYSTEM MUST BE CHECKED AND SECURED PRIOR TO USING 418-OR-3TW

MJM International Corporation www.mjminternational.com

1-800-270-6199

Fax: (956) 781-5552 hmoroles@yahoo.com

REV. C Date: 17-02-11 Page 2 of 2